

Unit Walk - Condition Ratings and Photos




Property Name: ████████████████████



BATHROOM AIR HANDLER

Rating	Count
Good	25
Repair	7
Replace	224



PHOTOS



Good Unit 3103



Good Unit 3003



Good Unit 3102




Good Unit 4703



Good Unit 4708



Good Unit 3005



Good Unit 4802



Good Unit 3107




Good Unit 4704



Repair Unit 3104




Repair Unit 3108




Repair Unit 1402



Repair Unit 3002




Repair Unit 3004




Repair Unit 1418



Repair Unit 2903




Replace Unit 4110



Replace Unit 4112



Replace Unit 4112



Replace Unit 3704



Good Unit 4704



Repair Unit 3104




Repair Unit 3108



Repair Unit 1402



Repair Unit 3002



Repair Unit 3004




Repair Unit 1418



Repair Unit 2903




Replace Unit 4110



Replace Unit 4112



Replace Unit 4112



Replace Unit 3704




Replace Unit 1408



Replace Unit 3801



Replace Unit 3803



Replace Unit 3803




Replace Unit 3613



Replace Unit 2112



Replace Unit 2110




Replace Unit 2104



Replace Unit 2018




Replace Unit 2004



Replace Unit 2001




Replace Unit 2101




Replace Unit 4610



Replace Unit 4701



Replace Unit 4505



Replace Unit 4506



Replace Unit 4608



Replace Unit 4507



Replace Unit 3101



Replace Unit 2908



Replace Unit 2114




Replace Unit 3001



Replace Unit 4412



Replace Unit 2901



Replace Unit 4409



Replace Unit 4303




Replace Unit 4308



Replace Unit 3816



Replace Unit 3804



Replace Unit 3806



Replace Unit 1405



Replace Unit 1407




Replace Unit 3007



Replace Unit 2111



Replace Unit 3603



Replace Unit 3606




Replace Unit 2106




Replace Unit 2115



Replace Unit 1904




Replace Unit 4809



Replace Unit 4804




Replace Unit 2002




Replace Unit 4605



Replace Unit 4516




Replace Unit 4601



Replace Unit 4501



Replace Unit 4515



Replace Unit 4208




Replace Unit 3902



Replace Unit 4102




Replace Unit 4001



Replace Unit 3904



Replace Unit 4007




Replace Unit 4007



Replace Unit 3907



Replace Unit 3615




Replace Unit 3707



Replace Unit 1404



Replace Unit 3605



Replace Unit 2108




Replace Unit 2109




Replace Unit 1907




Replace Unit 4801



Replace Unit 4614



Replace Unit 4609



Replace Unit 4405



Replace Unit 4305



Replace Unit 4201




Replace Unit 3903



Replace Unit 3812



Replace Unit 3918



Replace Unit 3908



Replace Unit 3706




Replace Unit 3701




Replace Unit 3616



Replace Unit 3609




Replace Unit 3609



Replace Unit 3609




Replace Unit 2107



Replace Unit 2006



Replace Unit 2105



Replace Unit 2003



Replace Unit 1908



Replace Unit 0608




Replace Unit 4616



Replace Unit 4504



Replace Unit 4612




Replace Unit 4612



Replace Unit 4509



Replace Unit 4514



Replace Unit 2904



Replace Unit 4416



Replace Unit 4408



Replace Unit 4407



Replace Unit 4218




Replace Unit 3808




Replace Unit 4101



Replace Unit 3901




Replace Unit 4105



Replace Unit 4005



Replace Unit 3906




Replace Unit 3906



Replace Unit 3905



Replace Unit 3811



Replace Unit 3708



Replace Unit 3612



Replace Unit 3612




Replace Unit 2102



Replace Unit 1901




Replace Unit 1903



Replace Unit 0606



Replace Unit 4806



Replace Unit 4706



Replace Unit 4512




Replace Unit 4502



Replace Unit 2902




Replace Unit 4114




Replace Unit 4413



Replace Unit 4306



Replace Unit 4202



Replace Unit 4206




Replace Unit 3809



Replace Unit 3604




Replace Unit 3718



Replace Unit 3705



Replace Unit 3703




Replace Unit 3610



Replace Unit 3607




Replace Unit 2113



Replace Unit 4803



Replace Unit 4503



Replace Unit 2907



Replace Unit 4611



Replace Unit 4510



Replace Unit 4508



Replace Unit 3006



Replace Unit 2906



Replace Unit 4404




Replace Unit 4403




Replace Unit 4204




Replace Unit 4401




Replace Unit 4302




Replace Unit 4302




Replace Unit 4302




Replace Unit 4705



Replace Unit 4705




Replace Unit 4606



Replace Unit 4606




Replace Unit 4602




Replace Unit 4615



Replace Unit 4513



Replace Unit 4607



Replace Unit 3105




Replace Unit 3105




Replace Unit 2902




Replace Unit 2902



Replace Unit 4415




Replace Unit 4415




Replace Unit 4415




Replace Unit 4304




Replace Unit 3602




Replace Unit 2110




Replace Unit 2110




Replace Unit 2108




Replace Unit 2108



Replace Unit 2109




Replace Unit 2109



Replace Unit 2109




Replace Unit 2018




Replace Unit 2018




Replace Unit 2018




Replace Unit 2018



Replace Unit 2004



Replace Unit 0608




Replace Unit 4808




Replace Unit 3004

BATHROOM BATHTUB / SHOWER FAUCET


Rating	Count
Good	17
Repair	3
Replace	236




PHOTOS



Repair Unit 0605




Repair Unit 0606




Replace Unit 1905




Replace Unit 1902




Replace Unit 2004



Replace Unit 2003




Replace Unit 0604




Replace Unit 0603




Replace Unit 2002




Replace Unit 0618




Replace Unit 1901




Replace Unit 0602



Replace Unit 0608




Replace Unit 0601




Replace Unit 0601



Replace Unit 1908




Replace Unit 1903




Replace Unit 1906



Replace Unit 1904




Replace Unit 2001



Replace Unit 1907

BATHROOM BATHTUB / SHOWER SURROUND


Rating	Count
Good	19
Repair	3
Replace	234














PHOTOS

BATHROOM COUNTERTOPS

Rating	Count
Good	18
Replace	238




PHOTOS





Replace Unit 2105



Replace Unit 2003



Replace Unit 1908



Replace Unit 0608




Replace Unit 4616



Replace Unit 4504



Replace Unit 4612



Replace Unit 4612



Replace Unit 4509



Replace Unit 4514



Replace Unit 2904



Replace Unit 4416



Replace Unit 4408



Replace Unit 4407



Replace Unit 4218



Replace Unit 3808